Arrow Well Testing & Septic PO Box 1415 Conifer, CO 80433-1415 (303) 838-1355



PROPERTY ADDRESS:	59 County Road 115, Bailey, CO		COUNTY:	Park
BUYER:	Dreamland Properties		ORDERED BY:	John Sanchez
BRÓKER:	John Wood		ORDER DATE:	1/24/2013
TEST DATE/TIME:	01/31/13 12:00 PM			
TEST DATE THAT.	07/01/10 12:00 1 1/1			
WELL RECOVERY TEST				
SIZE OF PUMP:	n/a AMPS:	5.8	_VOLTAGE:	230
WELLHEAD:		Well-X-Tro WX 202	_well storage:	477+ gailons
TOTAL PUMPED OUT:	477.9 gallons LENGTH OF TEST	02 hours 10 minutes	_AVG GPM:	n/a
RECOVERY GPM:	3			
STORAGE SYSTEM:	no above ground storage other than pressure tank			
COMMENTS:	According to State Records, the well a permitted in 1994 for Household Use C rate for this well was found to be approased a permitted in 1994 for Household Use C rate for this well was found to be approased a constant pump rate without running c test). When evaluating these numbers Resources assumes each person in a nine of the following on-line publication Please contact the State Division of W	Only (permit info is deemed eximately 3 gallons per mini proves the well is capable of try (constant meaning less s, please keep in mind that household uses approxima of or details: http://www.wa	I reliable, but not gute (3 gallons per forceucing at leas than 5% variation the State of Colorately 75 gallons of ter.state.co.us/pub	puaranteed). The recovery minute is approx equal to at 477 gallons and reaches over the final hour of the ado, Division of Water water per day. See page ps/wellpermitguide.pdf.
THIS TEST HAS BEEN CONDUCTED WITHIN THE GUIDELINES ESTABLISHED IN THE RULES AND REGULATIONS OF THE BOARD OF EXAMINERS OF WATER WELL CONTRACTORS, COLORADO DIVISION OF WATER RESOURCES. THIS TEST INDICATES THE WELL PRODUCTION ON THIS DATE. BECAUSE OF THE MANY VARIABLES THAT INFLUENCE A WELL'S PRODUCTION, WE OO NOT GUARANTEE THESE RESULTS BEYOND THE DATE OF THE TEST.				
SEPTIC HEALTH INSPECTION (Please Also Refer To Park County Septic Documentation)				
# OF BEDROOMS:	2	HOME OCCUPIED:	no	
SOIL CONDITIONS:	WET X DRY	SNOW COVERED	FROZEN	DAMP
RAW SEWAGE VISIBLE:	YES X NONE ABOVE	GROUND		
TALL WEEDS VISIBLE:  TYPE OF TANK:	YES NO	C 0/ 407/0 744//		
TIFE OF INN.		PLASTIC TANK		
	CONCRETE BAFFLES OTHER:	SEPTIC 'T's"		
SIZE OF TANK:				
CONDITION OF SYSTEM:	appears to be a 1000 gallon concrete	e tank	****	
COMMENTS:				
Jumen 13.	**Please note that the house was unoccupied at the time of inspection, which may hide areas of potential concern, as the system was not under normal load conditions. Also note that the tank was frozen at the time of inspection, which may hide areas of concern (although none were noted). I recommend re-inspecting the system when it is under normal load conditions. ** This system appears to consist of a single 1000 gallon, dual-compartment, concrete septic tank, and two absorption fields, with a diverter valve (County records indicate two 10x22 fields). The diverter valve cap should be replaced. I recommend alternating the absorption fields on an annual basis. A visual inspection of the system revealed no obvious signs of failure. The condition of the septic system is deemed acceptable at this time.			
THIS INSPECTION WAS CONDUCTED SOLELY FOR THE PURPOSE OF DETECTING HEALTH HAZARDS OBSERVABLE AT THE TIME OF INSPECTION, AND DOES NOT CONSTITUTE A WARRANTY THAT THE SYSTEM IS WITHOUT FLAW OR THAT IT WILL CONTINUE TO FUNCTION IN THE FUTURE. INSPECTIONS REQUESTED DURING PERIODS OF RAIN, SNOW COVER, OR WHEN A RESIDENCE IS UNOCCUPIED MAY BE OF REDUCED ACCURACY.				
NÉITHER ARROW WELL TESTING NOR ITS EMPLOYEES UNDERTAKE OR ASSUME ANY LIABILITY TO THE OWNER OF THE ABOVE PROPERTY, OR TO ANY PURCHASER OF THE ABOVE PROPERTY IN CONNECTION WITH THE EXAMINATION OF THE PROPERTY OR THE SUBSEQUENT REPORT.				
SIGNATURE:	Andy Angerson	WATER QUA	ECOVERY TEST: NLITY ANALYSIS: TH INSPECTION	\$ 40

TOTAL CHARGE:

\$ 380